

00862.022116



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

KAZUMA SATO et al.

Appl. No.: 09/781,162

Filed: February 13, 2001

For: METHOD, SYSTEM AND MEDIUM
FOR REMOTELY MANAGING
PLURAL IMAGE FORMING
APPARATUSES AND PLURAL
TYPES OF MAINTENANCE
AGREEMENTS RELATING TO THE
APPARATUSES
(As Amended)

U.S. Patent No.: 7,158,946 B2

Issued: January 2, 2007

Examiner: A. Shah

Group Art Unit: 3625

October 2, 2007

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

**Certificate
OCT 05 2007
of Correction**

**CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

10/04/2007 MAHMED1 00000011 7158946


01 FC:1811

100.00 OP

OCT 5 2007

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Edward A. Kmett
Attorney for Patentees
Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

FCBS_WS 1476016v1

OCT 5 2007

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,158,946 B2
DATED : January 2, 2007
INVENTOR(S) : Sato et al.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

PAGE TWO OF COVER SHEET:

(56) Foreign Patent Documents,

"JP 11-103291 10/2006" should read
-- JP 11-103291 4/1999 --.

SHEET 27:

FIG. 27, "COLLECTE" should read COLLECT.

SHEET 30:

FIG. 30, "STSTEM" should read SYSTEM.

COLUMN 1:

Line 15, "such" should read -- such as --; and
Line 67, "grasped" should read -- grasped. --.

COLUMN 5:

Line 56, "embodiment;" should read -- embodiment. --.

COLUMN 7:

Line 16, "need" should read -- needs to --.

OCT 5 2007

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,158,946 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,158,946 B2
DATED : January 2, 2007
INVENTOR(S) : Sato et al.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 8:

LINE 65, "re-freed" should read -- re-feed --.

COLUMN 9:

Line 1, "re-freed" should read -- re-feed --.

COLUMN 13:

Line 28, "tan" should read -- than --;
Line 40, "need only" should read -- needs only the --;
Line 57, "Detailed" should read -- Details --; and
Line 62, "shows" should read -- show--.

COLUMN 14:

Line 33, "paper" should read -- paper sheets --.

COLUMN 16:

Line 18, "from" should read -- from a --.

COLUMN 18:

Line 55, "particulars" should read -- particular --.

COLUMN 21:

Line 60, "malefaction" should read -- malfunction.

OCT 5 2007

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,158,946 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,158,946 B2
DATED : January 2, 2007
INVENTOR(S) : Sato et al.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 27, "different" should read -- different in --.

COLUMN 25:

Line 34, "like" should read -- like is --; and
Line 61, "tan" should read -- than --.

COLUMN 29:

Line 15, "shows" should read -- show examples of display information. --;
Line 22, "as" should read -- in --;
Line 34, "ID" should read -- IDs";
Line 48, "device" should read -- devices --; and
Line 49, Delete "the" third occurrence.

COLUMN 30:

Line 2, " " spot" should read -- " "spot --; and
Line 56, "Fig, 33" should read -- FIG. 33 --.

COLUMN 31:

Line "amount" should read -- amounts --.

COLUMN 33:

Line 27, "ID." should read -- IDs. --.

COLUMN 35:

Line 38, "of(i)" should read -- of (i) --.

1007 5 2007

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,158,946 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,158,946 B2
DATED : January 2, 2007
INVENTOR(S) : Sato et al.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 36:

Line 50, "through" should read -- through an --.

COLUMN 37:

Line 25, "as" should read -- a --; and

Line 26, "of(i)" should read -- of (i) --.

FCHS_WS 1475969v1

OCT 5 2007

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,158,946 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,158,946 B2
DATED : January 2, 2007
INVENTOR(S) : Sato et al.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

PAGE TWO OF COVER SHEET:

(56) Foreign Patent Documents,

"JP 11-103291 10/2006" should read
-- JP 11-103291 4/1999 --.

SHEET 27:

FIG. 27, "COLLECTE" should read COLLECT.

SHEET 30:

FIG. 30, "STSTEM" should read SYSTEM.

COLUMN 1:

Line 15, "such" should read -- such as --; and
Line 67, "grasped" should read -- grasped. --.

COLUMN 5:

Line 56, "embodiment;" should read -- embodiment. --.

COLUMN 7:

Line 16, "need" should read -- needs to --.

OCT 5 2007

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,158,946 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,158,946 B2
DATED : January 2, 2007
INVENTOR(S) : Sato et al.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 8:

LINE 65, "re-freed" should read -- re-feed --.

COLUMN 9:

Line 1, "re-freed" should read -- re-feed --.

COLUMN 13:

Line 28, "tan" should read -- than --;
Line 40, "need only" should read -- needs only the --;
Line 57, "Detailed" should read -- Details --; and
Line 62, "shows" should read -- show--.

COLUMN 14:

Line 33, "paper" should read -- paper sheets --.

COLUMN 16:

Line 18, "from" should read -- from a --.

COLUMN 18:

Line 55, "particulars" should read -- particular --.

COLUMN 21:

Line 60, "malefaction" should read -- malfunction.

OCT 5 2007

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,158,946 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,158,946 B2
DATED : January 2, 2007
INVENTOR(S) : Sato et al.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 27, "different" should read -- different in --.

COLUMN 25:

Line 34, "like" should read -- like is --; and
Line 61, "tan" should read -- than --.

COLUMN 29:

Line 15, "shows" should read -- show examples of display information. --;
Line 22, "as" should read -- in --;
Line 34, "ID" should read -- IDs";
Line 48, "device" should read -- devices --; and
Line 49, Delete "the" third occurrence.

COLUMN 30:

Line 2, " " spot" should read -- " "spot --; and
Line 56, "Fig, 33" should read -- FIG. 33 --.

COLUMN 31:

Line "amount" should read -- amounts --.

COLUMN 33:

Line 27, "ID." should read -- IDs. --.

COLUMN 35:

Line 38, "of(i)" should read -- of (i) --.

OCT 5 2007

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,158,946 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,158,946 B2
DATED : January 2, 2007
INVENTOR(S) : Sato et al.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 36:

Line 50, "through" should read -- through an --.

COLUMN 37:

Line 25, "as" should read -- a --; and

Line 26, "of(i)" should read -- of (i) --.

FCHS_WS 1475969v1

5 2007

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,158,946 B2

No. of add'l. copies
@ 30¢ per page

